



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
June 12, 2006

Supervisor 

Mine Name: JB Mine
Operator Name: Breccia Development
Mark Dotson
1208 S 200 W
PO Box 492
Milford, Utah 84751
Inspector(s): Tom Munson
Other Participants: none
Mine Status: Reclaimed

Permit number: S/001/054
Inspection Date: 5/3/2006
Time: 1:30 PM

Weather: Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, sign, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

To confirm the reclamation status of this mine. This mine was not actively mined but merely a remining of historic mine dumps. The BLM had released this site by letter on September 6, 2005 but because of our rules (which require waiting until three years has passed since the last seeding) and also the fact the Division had never visited the site, a release of the site could not be granted until after this inspection.

Inspection Summary:

Having not seen the site prior to mining, it was necessary to have the BLM verify that no disturbance had taken place other than the dump removal. The pit has obvious old vegetation in it and the old dumps of material also had old vegetation growing on them. The pit and dump are considered prelaw.

Conclusions and Recommendations:

Photos were taken. It was necessary to wait the appropriate amount of time (3 years since the last seeding) before a release could be granted. The site has no reclamation bond, so no bond money will need to be released. It is recommended that site be released

Inspector's Signature



Date: 06/13/2006

Inspection Date 05/03/2006;; Report Date: 06/12/06
Page 2 of 2
S/001/054

Directions to Site:

West of Milford, Utah in Pine Valley or the Indian Peak mountains

tm:jb

cc: Mark Dotson
Ed Ginuouves, BLM Fillmore

Attachment: Photos

O:\M001-Beaver\S0010054-JBmine\inspections\inspection05032006.doc

JB mine S/001/054



OLD PIT



OLD VEGETATION

OLD DUMPS



OLD PIT

JB mine 5/001/054



ALL OVER DISTURBANCE

